

# TABLE OF CONTENTS

## FORWARD

WARRANTY POLICY AND PROCEDURE ..... 3-5

## MT22/R/N/H AXLE

DIFFERENTIAL CARRIER HOUSING MT22/R/N/H ..... 6-7

DIFFERENTIAL MT22/R/N/H ..... 8-9

DIFFERENTIAL CARRIER HOUSING MTL22 ..... 10-11

DIFFERENTIAL MTL22 ..... 12-13

DIFFERENTIAL LOCK AIR CHAMBER MTL22 ..... 14-15

AXLE HOUSING MT22/R/N/H ..... 16-17

AXLE SHAFT ASSEMBLY MT22/R/N/H 2005 and Older ..... 18-19

AXLE SHAFT ASSEMBLY MT22/R/N/H 2005 and Newer ..... 20-21

PLANETARY MT22/R/N/H ..... 22-23

WHEEL HUB, BRAKE DRUM MT22/R/N/H ..... 24-25

BRAKE MT22/R/N/H ..... 26-27

TIE-ROD MT22/R/N/H ..... 28-29

Marmon-Herrington



13001 Magisterial Drive • Louisville, KY 40223  
(502) 253-0277 • (800) 227-0727 • Fax (502) 253-0317  
E-mail: [info@marmon-herrington.com](mailto:info@marmon-herrington.com)  
[www.marmon-herrington.com](http://www.marmon-herrington.com)